



SMITHERS
QUALITY ASSESSMENTS

CERTIFICATE OF APPROVAL

This is to Certify that the Quality Management System of:

Medina Plating Corporation

940 Lafayette Road, Medina, OH 44256

910 Lake Road, Medina OH 44256

(Page 1 of 2; see Appendix)

has been assessed and approved by Smithers Quality Assessments, Inc., to the following quality management system standards and requirements:

IATF 16949:2016 without Product Design

The Quality Management System is Applicable to:

The provision of zinc and zinc alloy plating.

Approval

Certificate Number: 04.301.2A

Current Certificate: 10/1/2018

IATF certificate number: 0336531

Certificate Expires: 9/30/2021



The use of the accreditation mark indicates accreditation in respect of those activities covered by the above certificate number.


on behalf of SQA - J. Michael Hochschwender, CEO

The approval is subject to the company maintaining its system to the required standards which will be monitored by Smithers Quality Assessments, Inc., 121 S. Main St. Suite 300, Akron, Ohio 44308, USA



APPENDIX A

Approval Certificate Number: 04.301.2A
IATF Certificate Number: 0336531



Page 2 of 2

SMITHERS QUALITY ASSESSMENTS, INC.

Site:

Medina Plating Corporation
940 Lafayette Road
Medina, OH 44256
Scope of services provided by this location: Plating

This registration is supported by the following extended manufacturing site:

Medina Plating Corporation
910 Lake Road
Medina, OH 44256
Scope of services provided by this location: Extended manufacturing site

This registration is supported by the following remote support location:

Medina Plating Corporation
930 Lafayette Road
Medina OH 44256
Scope of services provided by this supporting location: Logistics and warehousing

Applicable Standard: IATF 16949:2016 without Product Design

This appendix applies only to those sites listed above. As other sites are assessed and approved, or as sites already approved are removed from active services, this appendix will be amended to show the current status. Sites not listed on this appendix shall not be viewed as approved.

